

Inspection	Probe Type	Model	Inspecting For	True Position	Surface Profile	Capabilities	Variable Data Collection	Tight Space Data Collection	Tight Tolerance Data Collection	Multiple Features Checks	Works Across Multiple Gages	Surface SPC Checks	3rd Axis Capabilities	Wireless Connection	Digital Readouts in Handle	Specifications	Max Hole Diameter (mm)	Shaft Diameter (mm)	Shaft Length (mm)	Accuracy +/- (mm)	Repeatability +/- (mm)	Diametrical Range (mm)	Preset Distance (mm)	Part / Surface Offset (mm)	Data Collection	Manual	Data Collector	Preset Indicator	LMI 200	Includes	Zero Master Bushing	Case	Certification	Wireless Kit	Interchangeable Rods	Additional Requirements	Data Collector	Preset Indicator or LMI 200	Zero Calibration Block	LVDT			
Manual	Digital	TP101		*			*			*	*				*		23.62	25.40	81.28	0.01	0.01	3.17	N/A	N/A		*					*												
Manual	Digital	TP101L		*			*			*	*				*		23.62	25.40	132.08	0.01	0.01	3.17	N/A	N/A		*					*												
Manual	Digital	TP102		*			*			*	*			*	*		23.62	25.40	81.28	0.01	0.01	3.17	N/A	N/A		*	*			*	*	*	*					*					
Manual	Digital	TP102L		*			*			*	*			*	*		23.62	25.40	132.08	0.01	0.01	3.17	N/A	N/A		*	*			*	*	*	*					*					
Manual	Digital	TP103		*			*			*	*			*	*		23.62	31.75	81.28	0.01	0.01	6.00	N/A	N/A		*	*			*	*	*	*					*					
Manual	Digital	TP103L		*			*			*	*			*	*		23.62	31.75	132.08	0.01	0.01	6.00	N/A	N/A		*	*			*	*	*	*					*					
Manual	Digital	TP104		*			*			*	*			*	*		23.62	31.75	81.28	0.01	0.01	6.00	N/A	N/A		*				*	*	*	*										
Manual	Digital	TP104L		*			*			*	*			*	*		23.62	31.75	132.08	0.01	0.01	6.00	N/A	N/A		*				*	*	*	*										
Manual	Manual	TP105		*	*		*			*	*	*					23.62	25.40	81.28	0.020	0.020	3.170	N/A	N/A			*	*		*	*	*	*						*				
Manual	Manual	TP106		*	*		*			*	*	*					23.62	31.75	81.28	0.020	0.020	3.170	N/A	N/A			*	*		*	*	*	*						*				
Manual	Analog	TP107		*	*		*	*		*	*	*					23.62	31.75	81.28	0.020	0.010	6.000	N/A	N/A			*	*		*	*	*	*						*	*	*		
Manual	Analog	TP107L		*	*		*	*		*	*	*					23.62	31.75	132.08	0.020	0.010	6.000	N/A	N/A			*	*		*	*	*	*					*	*	*			
Manual	Analog	TP108		*	*		*	*		*	*	*					23.62	25.40	81.28	0.020	0.010	3.170	N/A	N/A			*	*		*	*	*	*					*	*	*			
Manual	Analog	TP108L		*	*		*	*		*	*	*					23.62	25.40	132.08	0.020	0.010	3.170	N/A	N/A			*	*		*	*	*	*					*	*	*			
Manual	LVDT	TP109		*			*		*	*	*						23.62	25.40	81.28	0.005	0.005	3.170	N/A	N/A		*			*	*	*	*					*	*	*		*		
Manual	LVDT	TP110		*			*		*	*	*						23.62	31.75	81.28	0.005	0.005	6.000	N/A	N/A		*			*	*	*	*					*	*	*		*		
Automated	Pneumatic	AP110		*	*		*			*	*		*				23.62	N/A	N/A	0.005	0.005	6.000	N/A	N/A		*			*	*	*	*					*	*	*		*		
Automated	Pneumatic	AP111		*	*		*			*	*		*				23.62	N/A	N/A	0.005	0.005	6.000	N/A	N/A		*			*	*	*	*					*	*	*		*		
Manual	3rd Axis Probe	TP111-31-80		*			*			*	*		*				N/A	25.40	N/A	N/A	N/A	N/A	31.00	80.00			*	*		*	*	*	*			*	*	*		*			
Manual	3rd Axis Probe	TP111-31-95		*			*			*	*		*				N/A	25.40	N/A	N/A	N/A	N/A	31.00	95.00			*	*		*	*	*	*			*	*	*		*			
Manual	3rd Axis Probe	TP111-50-80		*			*			*	*		*				N/A	25.40	N/A	N/A	N/A	N/A	50.00	80.00			*	*		*	*	*	*			*	*	*		*			
Manual	3rd Axis Probe	TP111-50-95		*			*			*	*		*				N/A	25.40	N/A	N/A	N/A	N/A	50.00	95.00			*	*		*	*	*	*			*	*	*		*			
Manual	3rd Axis Probe	TP112-31-65		*			*			*	*		*				N/A	31.75	N/A	N/A	N/A	N/A	31.00	65.00			*	*		*	*	*	*			*	*	*		*			
Manual	3rd Axis Probe	TP112-31-80		*			*			*	*		*				N/A	31.75	N/A	N/A	N/A	N/A	31.00	80.00			*	*		*	*	*	*			*	*	*		*			
Manual	3rd Axis Probe	TP112-50-65		*			*			*	*		*				N/A	31.75	N/A	N/A	N/A	N/A	50.00	65.00			*	*		*	*	*	*			*	*	*		*			
Manual	3rd Axis Probe	TP112-50-80		*			*			*	*		*				N/A	31.75	N/A	N/A	N/A	N/A	50.00	80.00			*	*		*	*	*	*			*	*	*		*			
Manual	3rd Axis Probe	TP112-50-95		*			*			*	*		*				N/A	31.75	N/A	N/A	N/A	N/A	50.00	95.00			*	*		*	*	*	*			*	*	*		*			